

2001 Ford Windstar LX

2001 ACCESSORIES & EQUIPMENT Module Communications Network - Windstar

INSTRUMENT CLUSTER MODULE DIAGNOSTIC TROUBLE CODE INDEX

DTC	Description	Perform Test
B1202	Fuel Sender Circuit Open	(1)
B1204	Fuel Sender Circuit Short To Ground	(1)
B1205	ICM Switch 1 Assembly Circuit Failure (Open Or Short To Power)	(1)
B1213	Number Of Programmed Ignition Keys Is Below Minimum	(2)
B1232	Antenna Not Connected Defective Transceiver	(2)
B1246	Dim Panel Potentiometer Switch Circuit Failure	(1)
B1249	Blend Door Failure	(3)
B1342	ECU Defective	(4)
B1346	Heated Backlite Input Circuit Short To Ground	(5)
B1352	Ignition Key-In Circuit Failure	(1)
B1470	Headlamp Input Circuit Failure	(6)
B1600	PATS Ignition Key Transponder Signal Is Not Received - Non PATS Key Or Damaged Key	(2)
B1601	PATS Received Incorrect Key-Code From Ignition Key Transponder - Unprogrammed Encoded Ignition Key	(2)
B1602	PATS Received Invalid Format Of Key-Code From Ignition Key Transponder - Partial Key Read	(2)
B1676	Battery Voltage Out Of Range	(1)
B1681	PATS Transceiver Signal Is Not Received - Not Connected, Damaged Or Damaged Wiring	(2)
B1875	Turn Signal/Hazard Switch Signal Circuit Failure	(6)
B2103	Antenna Not Connected Defective Transceiver	(2)
B2139	PCM ID Does Not Match Between Instrument Cluster & PCM	(7)
B2141	NVM Configuration Failure - No PCM ID Exchanged Between Instrument Cluster & PCM	(2)
B2175	A/C Signal Circuit Short To Ground	(3)
B2176	Overdrive Switch Circuit Short To Power	(8)
B2472	Fog Lamp Switch Failure	(6)
B2477	Module Configuration Failure	(9)
B2513	Blower (Fan) Circuit Failure	(3)
B2586	Headlamp Mode Circuit Failure	(6)
C1779	Blower Switch Failure	(3)
U1041	SCP Invalid Or Missing Data For Vehicle Speed	(10)
U1043	SCP Invalid Or Missing Data For Traction Control	(11)
U1051	SCP Invalid Or Missing Data For Brakes	

2001 Ford Windstar LX

2001 ACCESSORIES & EQUIPMENT Module Communications Network - Windstar

		(11)
U1073	SCP Invalid Or Missing Data For Engine Coolant	(10)
U1123	SCP Invalid Or Missing Data For Odometer	(11)
U1131	SCP Invalid Or Missing Data For Fuel System	(1)
U1147	Invalid Or Missing Data For Vehicle Security	(2)
U1262	Missing SCP Message	<u>M</u>
U2013	Compass Module - No Response	(1)

- (1) See ANALOG INSTRUMENT PANELS - WINDSTAR article for testing procedure.
- (2) See PASSIVE ANTI-THEFT SYSTEMS - WINDSTAR article for testing procedure.
- (3) Repair A/C system as necessary. See AUTOMATIC A/C-HEATER SYSTEMS - WINDSTAR article in AIR CONDITIONING & HEATING for testing procedure.
- (4) Using NGS tester, perform instrument cluster self-test. If DTC B1342 is retrieved again, replace instrument cluster.
- (5) See POWER WINDOWS - WINDSTAR article for testing procedure.
- (6) See AUTOLAMP SYSTEMS - WINDSTAR article for testing procedure.
- (7) See ACTIVE ANTI-THEFT SYSTEMS - WINDSTAR article for testing procedure.
- (8) See FORD AX4S ELECTRONIC CONTROLS in AUTOMATIC TRANSMISSIONS article for testing procedure.
- (9) See **MODULE CONFIGURATION** under PROGRAMMING.
- (10) Using NGS tester, perform PCM self-test.
- (11) Using NGS tester, perform ABS/Traction Control self-test.