



1990 ENGINE PERFORMANCE
Self-Diagnostics - 1.5L/1.6L Fuel Injected

AUTOTRONICA Y ELECTRONICA PORTUGAL


Fig. 1: ECU LED Location & Blinking Frequency Examples
1990 Honda Civic CRX Si



Separate Problems:



Simultaneous Problems:



50D16058