


Fig. 47: Exploded View of Timing Chain
 Courtesy of GENERAL MOTORS CORP.
 2003 Chevrolet TrailBlazer



- (1) Exhaust Camshaft Actuator Bolt
- (2) Timing Chain
- (3) Exhaust Camshaft Actuator
- (4) Intake Camshaft Sprocket
- (5) Timing Chain Guide
- (6) Timing Chain Guide Bolt
- (7) Crankshaft Sprocket

- (8) Crankshaft Balancer Friction Washer
- (9) Timing Chain Tensioner Bolt
- (10) Timing Chain Tensioner
- (11) Timing Chain Tensioner Shoe
- (12) Timing Chain Tensioner Shoe Bolt
- (13) Intake Camshaft Sprocket Bolt

G02128401